



**ALCO INC. HEAD OFFICE**  
6925 104 Street, Edmonton, Alberta T6H 2L5  
Office: (780) 435-3502  
Website: www.alcoinc.ca

July 18, 2019

Stuart Wood Ventures Ltd.  
9103 - 109 Avenue  
Fort St. John, B.C.  
V1J 7A8

### EQUIPMENT CERTIFICATION

---


<b>CUSTOMER:</b>	Stuart Wood Ventures Ltd.
<b>CUSTOMER EQUIPMENT # :</b>	N/A
<b>CUSTOMER RIG # :</b>	N/A
<b>EQUIPMENT DESCRIPTION:</b>	Alco Elevator Bushing
<b>MODEL AND RATING:      150 Tons</b>	4 1/2" - 90° - 150 Ton (133446-daN)
<b>INSPECTION COMPANY / REPORT #:</b>	Alco / H -34561
<b>ALCO ENGINEERING FILE # :</b>	73150-2-E
<b>ALCO WORK ORDER # :</b>	73150-2

---

This document certifies that all parts and /or assemblies for the Alco equipment referenced above have been manufactured using new materials and inspected in accordance with the customer's purchase order, as well as all applicable Alco Inc. specifications and procedures.

All material acceptances, dimensional inspections, proof and function tests and non-destructive testing inspections were performed by Alco Inc. qualified personal and meet Alco Inc. specifications as well as ductility requirements of API Specification 8C, 5th Edition 2012.

Brian Kulak, P.Eng  
Engineering Manager  
Alco Inc.





July 18, 2019

Stuart Wood Ventures Ltd.  
9103 - 109 Avenue  
Fort St. John, B.C.  
V1J 7A8

### EQUIPMENT CERTIFICATION

---

<b>CUSTOMER:</b>	Stuart Wood Ventures Ltd.
<b>CUSTOMER EQUIPMENT # :</b>	N/A
<b>CUSTOMER RIG # :</b>	N/A
<b>EQUIPMENT DESCRIPTION:</b>	Alco Elevator Bushing
<b>MODEL AND RATING:</b> <u>150 Tons</u>	5" - 90° - 150 Ton (133446-daN)
<b>INSPECTION COMPANY / REPORT #:</b>	Alco / H -34562
<b>ALCO ENGINEERING FILE # :</b>	73150-1-E
<b>ALCO WORK ORDER # :</b>	73150-1

---

This document certifies that all parts and /or assemblies for the Alco equipment referenced above have been manufactured using new materials and inspected in accordance with the customer's purchase order, as well as all applicable Alco Inc. specifications and procedures.

All material acceptances, dimensional inspections, proof and function tests and non-destructive testing inspections were performed by Alco Inc. qualified personal and meet Alco Inc. specifications as well as ductility requirements of API Specification 8C, 5th Edition 2012.

**Brian Kulak, P.Eng**  
Engineering Manager  
Alco Inc.

